CNC MACHINING & INSPECTION

Machined to your print.

Corvane Precision follows the drawing through machining, batch inspection and shipment.



Campaign example: machined aluminum brackets packed in a tray.

Machine to print

The drawing sets the part geometry, material and revision. In the film, an end mill cuts a pocket into an aluminum blank.

Inspect each batch

The part goes to the inspection bench. Identify the dimensions and drawing notes you want covered in the batch report.

Ship with the report

The finished parts are arranged for packing. The inspection report travels with the batch so receiving can check it against the drawing.

What to include in a quote request

Send the current drawing with its revision, part reference, quantity and material. List any features to document in the inspection report and any packing instructions.

Corvane Precision is a fictional manufacturer created for a portfolio. The campaign features a quote in two business days.